NPDES STORM WATER CONSTRUCTION COMPLIANCE INSPECTORS REPORT

NPDES	PERMIT NO.: <u>SCR10S877</u> DATE OF INSPECTION: <u>07/13/2016</u>
PROJEC ⁻	T NAME: North Augusta High School Phase IICOUNTY:Aiken/Report #8
PROJECT DESCRIPTION (check one):Residential Commercial:X_ OTHER: <u>Educational Facility</u>	
1.	TYPE OF INSPECTION
Χ	1) At least once every 7 calendar days
11.	WEATHER CONDITONS
Χ	1) Weather conditions during inspection: SUNNY/97/ HOT
Χ	2) Weather conditions since last inspection, including rainfall information: Rain O'
III.	
YES	1) Does this project have an approved permit?
NO	2) Are the erosion and sediment control measures installed and being maintained as shown on the approved Plan?
YES	3) Is erosion being controlled on the site?
YES	4) Is sediment being contained on the site?
NO	5) Are any adjacent properties or state waters being impacted?