


NPDES STORM WATER CONSTRUCTION COMPLIANCE INSPECTORS REPORT


NPDES PERMIT NO.: SCR10S877 DATE OF INSPECTION: 07/16/2016


PROJECT NAME: North Augusta High School Phase II COUNTY: Aiken/Report #9

PROJECT DESCRIPTION (check one): Residential Commercial: OTHER: Educational Facility

I.	TYPE OF INSPECTION
X	1) At least once every 7 calendar days
II.	WEATHER CONDITONS
X	1) Weather conditions during inspection: PARTLY SUNNY/88/ HOT
X	2) Weather conditions since last insp2ref30.36 348.79 0.48 19.56 re47998 A0 1 174.86 333.19 Tm0 g0 (









Maintenance still needed as of 7/16/2016