

**Site Visit Date: 12-11-19**

Time: 1:00 P:M
Site Conditions: Good

Distribution: (if different from above)

tractor's rights and responsibilities

mcmillanpazdansmith.com



architect's field report

The following information is for informational purposes only. Please report

Observations

1. Attached GAC materials.
2. Area A:
 - Masonry continues.
 - Rough in continues.
 - Setting column and lintels.
3. Area B:
 - Masonry continues.
 - Rough in continues.
 - Setting column and lintels.
4. Area C:
 - Slab pour.
 -

Architect's field report. The information contained herein is for informational purposes only. Please report any changes or updates to the project as they occur. Refer to AIA 201.4.2.2.


127 dunbar street, spartanburg, sc 29306
o. 864 585 5678 f. 864 542 9451

mcmillanpazdansmith.com



architect's field report

Background:



Architect's field report. You are to provide a field report. Refer to AIA 201.4.2.2.

sequences of tractor's rights and responsibilities.

127 dunbar street, spartanburg, sc 29306
o. 864 585 5678 f. 864 542 9451

mcmillanpazdansmith.com

